Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/15015SE-6074/1

Work Order Type: Weatherization

Audit Name: 15015SE-6074AUDIT

CLIENT INFORMATION

Client Name: NA Address:

Client ID: 15015SE-6074 Ocoee, TN 37361

Alt. Client ID: Polk

CLIENT CONTACT INFORMATION

NA Applicant/Person of Record 2000 Mobile home with Record 12x20 addition Approx 2088 sqft

AGENCY INFORMATION

Agency: Southeast Tennessee Human Resource Agency Agency Phone: (423) 949-2191

Address: 312 Resource Rd. **Fax:** (423) 949-4023

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Auditor: Darrell Bloodworth Cell: (423) 505-4585

Email: Darblood@comcast.net

Measures

	Measure 1 Air C	onditioning Seal and \	Winter Co	ver	Componer	its			Inspected
C	Comment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Air Conditioning Seal and Winter Cover	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
C	Other Detail								
				Measu	re Sub Total:			Sub Total:	
		Ducts all supply ducts and retu	urn to less	than 1	Componer	nts			Inspected
	omment in ocal c	an supply duote and rota	111 10 1000	triarr r	Estimated	ı		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Duct sealing (setup cost)	Each	1					
10	Miscellaneous Su	Duct Sealing	Each	12					
C	Other Detail				7		-		
				Measu	re Sub Total:			Sub Total:	
	Field Notes:								

	corner b bedroom approx r feet, Livi	rom windows W-11 and ehind door approx seven door approx nine feet, nine feet, living room- caing room- caulk ceiling toom- caulk ceiling trim voom- caulk ceiling trim v	n feet, Livin Kitchen- ca ulk corner rim where t	ng rooi aulk co to righ two ha	m- caulk cor orner to right t of gas hea lves join app	ner at ma of refrige ter appro prox 20 fe	aster erator x nine	k	
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1					
10	Miscellaneous Su	Infiltration Reduction	See Above	1					
C	Other Detail								
Ī									
_				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Comment Adjust strike plate to compress weatherstripping on two doors, Remove

Components

Inspected

Measure 3 General Air Sealing

Measure 4 DV	/H Pipe Insulation			Componen	its		I	nspected
Comment								
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe Insulation	Linear Foot	10					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	DWH Pipe Insulation	Linear Foot	10					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	<i>Measure</i> 5 Addi Comment	ition floor insulation			Componer	nts			Inspected
	omment				Estimated	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fbergls, R19 batts	SqFt	240					
		Includes labor cost. Contractor to install using Resnet Grade 1 Standards. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Floor Insulation - Fbergls, R19 batts	SqFt	240					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Mea	asure 6 DWH	Tank Insulation			Componen	ts		1	nspected	
Com	nment									
					Estimated	<u> </u>		Actual		
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Ins	sulation	DWH Tank Insulation	Each	1						
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2 La	abor	DWH Tank Insulation	Each	1						
Othe	er Detail									
				Measur	re Sub Total:			Sub Total:		
Fie	eld Notes:									

Measure 7 CO	Monitor is Needed			Componen	ts			Inspected
Comment Refer to Field Gu	Attachment A- Standards uide.	s for Wea	theriza	ition Materia	ls and So	outheas	t	
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO monitor	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:							· ·	

1	Measure 8 Fix I	mproper Venting (Cloth	es Dryer))	Componen	ts			Inspected
C	protrudir is 15 fee	ents installed with dampering through pipe. Must be et. No changes allowed. Frization Materials and Sou	vented to Refer to A	outsid ttachm	le of home. Nent A-Stand	Maximum	length		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:						-		

Comment 30 # Material / Lab 1 Health and S			Exhaust	Į.	Componen	ts			Inspected
	inch r	ange hood not operation	nal		Estimated	1		Actual	
1 Health and S	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Safety	Equipment	Each	1					
2 Labor		Labor	Each	1					
Other Detail									
				Measur	e Sub Total:] ;	Sub Total:	
Comment Add cra fas	(Base dition of wlspace stened.	r Barrier Needed ement/CrawIspace) crawIspace. Must be 6 n ce with 6" turned up all v . Must be cleated down t ment A- Standards for V	valls and and to earth. N	suppor ⁄lust be	t piers. Mus secured at	0% of st be secu all seams	s. Refe	r	Inspected
	ide.	ment / Ctangargo for t	, oati 1011 <u>2</u>	20011 111			0111010		
					Estimated			Actual	
# Material / Lab1 Health and S		Description / Comment Basement /Crawlspace	<i>Units</i> SqFt	Qty 240	Unit Cost	Total	Qty	Unit Cost	Total
· ricaliir and c	odicty	Vapor Barrier	94. 1	2.10					
2 Labor		Labor	SqFt	240					
Other Detail									
				Measur	e Sub Total:			Sub Total:	
Field Notes:									

Client Name: NA Client ID: 15015SE-6074 Alt. Client ID: Polk Work Order (Bid Form)
Work Order Name: WO/15015SE-6074/1

Report Run On: 4/18/2010

DOE Weatherization Assistant
Version 8.6.0
Page 9 of 10